

61/c

BHARAT SANCHAR NIGAM LIMITED

(A Government of India Enterprise)

Office of the Divisional Engineer (Rural), ANAKAPALLI - 531001

Lr No.SDE (Gr-NTPC)/Electrical Corr/ 2024-25/03 Dated at NTPC the 18.09.2024

To

The AGM (CFA-Plg),
O/o GMTD VM,
VISAKHAPATNAM.

Subject: Request for Engine alternator Repair and Relocation at Achuthapuram Exchange-Reg.

It is to bring to your attention an urgent issue concerning the generator at the Achuthapuram exchange. During the vacating process of one portion of the facility, the generator was shifted to the entrance of the remaining portion. The generator is currently non-operational, and as we have already handed over the vacated portion to the owners, the placement of generator is obstructing access to the remaining portion.

Given the circumstances, I kindly request the following:

1. **Immediate Repair:** Please arrange for the generator to be repaired as soon as possible.
2. **Relocation:** Once repaired, the generator should be moved inside the Achuthapuram exchange to ensure unobstructed access to the remaining portion.

Your prompt attention to this matter would be greatly appreciated to avoid any further inconvenience.

P. J. Parvathi

Sub Divisional Engineer(NTPC-Gr)
O/o DE-Rural, Anakapalli.

Boon
19/9/2024


Copy to:

The DE (Rural), O/o GMTD VM – for info please.

The SDE(electrical) - for info please.



O/o Sub-Divisional Engineer (GPM),
BSNL BHAVAN, Telephone exchange,
Gopalapatnam, Visakhapatnam-27
Mob: +91 9491500899


BHARAT SANCHAR NIGAM LIMITED
(A Govt. of India Enterprises)

dated at GPM the 02.09.2024

Lr No: SDE(GPM)/General/2024-25/

To

The Assist. General Manager (Plg),
O/o PGMTD, BSNL BHAVAN
Dabagardens, VM-20

Respected Madam,

Sub: Seeking permission for rearrangement of Generator Changeover switch-reg.,

The recent reduction in staff at the Gopalapatnam exchange has prompted the need for a change in the daily operational procedures. Specifically, the location of the EB switch gear inside the exchange powerplant room has raised concerns regarding safety and security. As it stands, the powerplant room where switch gear panel is always locked when the exchange is unattended or left office in the evening which necessitating the provision of keys to security personnel to operate the generator changeover in the event of a power failure. However, recent theft attempts at the Gopalapatnam exchange and its premises have highlighted the potential risks associated with this setup. In light of these security concerns, it is imperative to seek permission to relocate the generator changeover arrangement outside the exchange premises. This would facilitate easier operation by the night watchman.

The proposed relocation of the generator changeover arrangement serves as a proactive measure to address the security challenges faced by the Gopalapatnam exchange. By situating the equipment outside the premises, it becomes more accessible to authorized personnel, particularly the night watchman responsible for overseeing operations during non-operational hours on EB power fail. Furthermore, the installation of CC cameras would provide added surveillance, strengthen security and deterring potential intrusions in to exchange premises. Our requests have been approved by the competent authority in previous letters pertaining to CC Camera, compound wall repair and new back gate arrangements for implementation. Upon careful consideration, it becomes apparent that the proposed changes align with the overarching goal of prioritizing safety and security at the Gopalapatnam exchange.

Moreover, it is requested to speed up the approved requests, specifically referencing compound wall repair and new gate arrangements CC cameras, which address the security and operational concerns within the exchange premises.


In conclusion, the request to relocate the generator changeover arrangement outside the Gopalapatnam exchange premises stands as a prudent and necessary step towards enhancing security and operational efficiency. By adhering to the directives of the competent authority and prioritizing safety measures, the proposed changes promise to fortify the resilience of the exchange against potential threats and streamline daily operational procedures for the benefit of all stakeholders involved.

Thanking you in advance for the favorable orders, please

Date: 02.09.2024

Copy to

1. The DGM (CFA) for information
2. The DE (Urban) for information and necessary approval


Sub-Divisional Engineer
Sub Divisional Engineer (External)
B.S.N.L., GOPALAPATNAM,
27/09/2024



O/o The Sub Divisional Engineer,
Telephone Exchange, Dabagardens,
BSNL, Visakhapatnam -530020




भारत संचार निगम लिमिटेड
(भारत संचार निगम लिमिटेड)
BHARAT SANCHAR NIGAM LIMITED
(A Govt. Enterprise)

Lr No.SDE-DBG/switch room/2024-25/01 dtd at Dabagardens, VM the 30/08/2024.

To
The AGM(N/W Planning)
O/o GMTD,
Dabagardens,
Visakhapatnam.

Sub : Repair of AC'S in Dabagarden Switch Room - reg

This is to inform that in Dabagardens Exchange switch room-1, where ONE inverter AC is not working and 2 NO of AC are getting water leaked. As it has MGPN LMG'S and other network elements. Also as was discussed that in Power Plant room, one of the incoming earth point was disconnected. So please arrange to rectify the above issues.


Sub Divisional Engineer
Telephone Exchange
Dabagardens Visakhapatnam

Copy to SDE(Electrical), VM

4g
Ramesh
30/08/2024
DE (W.M.)

Alr



भारत संचार निगम लिमिटेड
(भारत सरकार का उपक्रम)
BHARAT SANCHAR NIGAM LIMITED
(A Govt. of India Enterprise)

(Office of the Sub Divisional Engineer, Mindi, Visakhapatnam)
Lr.No.SDE-MND/ PLG COrr/2024-25/12

Dt:13.09.2024

AGM(Planning)
%GMTD
Visakhapatnam

Sub:request for arrange to replace the electrical panel at transformer room of
telephone exchange Mindi-Reg

Sir/madam

Electrical panel at transformer room was faulty due to that issue
Engine alternator was became fault and not working now.interruptions in
APSEB power supply occurring regularly at mindi area as it is rainy
season.To avoid exchange interruptions Engine alternator is very much
essential to run (while not available APSEB power supply) mainly at odd
hours .And for time being it is suggested to bring the mobile trolley generator
in to live which lies at mindi exchange only.

Hence this is here by requesting you that please arrange to replace the
electrical panel at transformer room and repair the engine alternator .

Sub divisional engener
BSNL/Mindi
viskhaatnam

Copy to
DE(south&rural) for info please